

# Oil Field Environmental Incident Summary

**Incident:** 20150804165844      **Date/Time of Notice:** 08/04/2015 16:58

**Responsible Party:** Hamm and Phillips Service Co.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** JERSEY 24-6H3

**Field Name:** ALKALI CREEK

**Well File #:** 27827

**Date Incident:** 8/4/2015      **Time Incident:** 12:00

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 153

**Rng:** 93

**Sec:** 6

**Qtr:**

**Location Description:**

**Submitted By:** Shane Knuchel

**Received By:**

**Contact Person:** Shane Knuchel  
10290 60th St NW  
Tioga, ND 58852

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0.1	Barrels	0.1	Barrels		
<b>Brine</b>	2	Barrels	2	Barrels		

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

All fluid contained on site. Approximately 100 feet long trail.

**Potential Environmental Impacts:**

Well site soil

**Action Taken or Planned:**

Manhole hatch was tightened, standing fluid was sucked up, and impacted material was removed and replaced.

**Wastes Disposal Location:** Prairie Disposal

**Agencies Involved:** Notified Bob Garbe NDIC by phone on 8/4/2015 at 04:45 PM CT.

**Updates**

---

**Date:** 8/5/2015      **Status:** Reviewed - Assigned to Other Agency

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a tank leak, remained on location according to the report. NDIC retains oversight.